

Does this work? Where to place the 12V – Battery On Ultraborg Board or Thunderborg Board? I would prefer Thunderborf Board





Here I need only 1 x 5V